



1	(ENDURO) SHIFT WASHER 18x315x07 ME25636014 (u. 2)
2	(ENDURO) PRIMARY II PINION ME25636071 (u. 1)
3	RJ-MR CIRCLIP DIN 471 : 25049255 : ME25936084 0/000.300.9107 (u. 3)
4	(ENDURO) GROOVING WASHER 315x(25x22)x1 ME25636091 (u. 2)
5	(ENDURO) PRIMARY VI PINION ME25636074 (u. 1)
6	PRIMARY III AND IV PINION {GASGAS EC/XC 18→ , RIEJU MR 21→} ME25636072 (u. 1)
7	GEAR WASHER 25.2x31.5x1 ME25636017 (u. 2)
8	(ENDURO) PRIMARY V PINION ME25636073 (u. 1)
9	RJ-GEAR BEARING K25-29-10 : M02616000 0/000.960.9104 (u. 1)
10	(ENDURO) PRIMARY AXLE : ME25636070 ME250236070 (u. 1)
11	(ENDURO) SECONDARY AXIS ME410002508 (u. 1)
12	CIRCLIP DIN 983 D.25 (25049255) ME25636095 (u. 1)
13	(ENDURO) SECONDARY PINION II ME42211GG-CSK-1 (u. 1)
14	(ENDURO) SECONDARY PINION VI ME42215GG-CSK-1 (u. 1)
15	SECONDARY III PINION ME25636078 (u. 1)
16	SECONDARY IV PINION ME25636079 (u. 1)
17	SECONDARY V PINION ME25636080 (u. 1)
18	(ENDURO) GEAR WASHER 208x29x1 ME25636016 (u. 1)
19	RJ-MR NEEDLES BEARING K20x24x10 : ME25636059 0/000.960.9114 (u. 1)
20	(ENDURO) SECONDARY I PINION (2001-2019) ME25636076 (u. 1)

<b>21</b>	CIRCLIP D.25 DIN 471 SE03025200009 (u. 1)
<b>22</b>	RJ-FRONT SPROCKET *13T* : ME25636025 0/005.400.9112 (u. 1)
<b>22A</b>	RJ-MR (FRONT) SPROCKET 12 TOOTH : MF25836025 0/005.400.9113 (u. 1)
<b>23</b>	RJ-MR SEAL BUSHING (2001-2019) : ME25636046 0/000.260.9100 (u. 1)
<b>24</b>	RJ-MR C/SHAFT SPROCKET O-RING 25x2 : ME25632025 0/000.490.9107 (u. 2)
<b>25</b>	RJ-MR SHIFT BEARING 6305 : 00042155-0 : ME25636058 0/000.960.9113 (u. 1)
<b>26</b>	RJ-MR SHIFT BEARING 6203 : MIT50012006, Y00.126027 : ME25636057 0/000.960.9112 (u. 2)
<b>27</b>	RJ-SHIFT BEARING 6205ZC3E {GASGAS 02-19, RIEJU MR 20->} : ME250136056 0/000.960.9106 (u. 1)
<b>28</b>	RJ-COUNTERSHAFT SEAL PRO 30x40x7 : ME25636024 0/000.890.9106 (u. 1)
<b>29</b>	RJ-MR NEEDLES BEARING KD22x25x98 : ME250236102 0/005.150.9101 (u. 4)
<b>30</b>	RJ-MR CIRCLIP DIN 471 : 25049255 : ME25936084 0/000.300.9107 (u. 1)
<b>31</b>	RJ-MR SHIFT GEAR SET : ME40000CT-CSK-1 0/005.400.9107 (u. 1)