



1	RJ-ELECTRIC START KIT {RIEJU MR 22} 0/005.480.9102 (u. 1)
2	ALLEN BOLT 5x25 : T0205025, T0315025N : T0305025 0/000.460.9146 (u. 5)
3	RJ-ROTOR {RIEJU MR 21->} 0/005.820.9102 (u. 1)
4	RJ-MR ELECTRIC START SPROCKET : EE80200GG-CBR-2 0/005.400.9102 (u. 1)
5	TORX SCREW 5x8 : 050808BB : T0455008 0/000.460.9154 (u. 3)
6	FLYWHEEL BOLT 10x25 : T02010020 : T02010025 0/000.460.9112 (u. 1)
7	(ENDURO) IGNITION COVER ME60100GG-CBR-3 (u. 1)
8	HEAD SCREW 6x40 : MFS400116351 : T0206040 0/000.460.9125 (u. 1)
9	HEAD SCREW 5x15: T0205015/2, T0205010 : T0205015 0/000.460.9115 (u. 3)
11	ALLEN BOLT 5x10 : T0315012 : T0305010 0/000.460.9145 (u. 2)
12	RJ-STARTER COVER KIT + BENDIX IMPROVED : 0/005.400.9115 0/005.480.9103 (u. 1) RJ-OBSOLETE : EE80110CT-CBR-1 0/005.480.9103 : MR COMPLETE BENDIX 0/005.400.9115 (u. 1)
13	BENDIX GEAR COVER {RIEJU} EE80130GG-CBR-2 (u. 1)
14	RJ-MR ELECTRIC E-START MOTOR (2015-2019) : EE80000GG-CBR-2 0/005.480.9100 (u. 1)
15	RJ-BENDIX COVER GASKET {GASGAS EC/XC} EE80135GG-CBR-1 (u. 1)
19	RJ-MR STARTER ENGINE BRACKET : EE80050GG-CBR-3 0/000.980.9111 (u. 1)
22	(ENDURO) C-CLIP 28x1.2 EE80055GG-CBR-1 (u. 1)
24	(ENDURO) PIN 3x9.8 EE80140GG-CBR-1 (u. 2)
25	FLANGE BOLT 6x25 10.9 : T0206025/2 : T0206025 0/000.460.9121 (u. 3)

27	RJ-MR PULSER COIL ADAPTOR : EE70216GG-CAB-1 : EE70216GG-CAB-2 0/000.980.9109 (u. 1)
28	RJ-MR IGNITION GASKET COVER (2019) : ME94500GG-CSK-1 0/000.490.9119 (u. 1)
29	FLANGE NUT 6mm : T2306000 : T2206000 0/000.340.9116 (u. 1)
30	WASHER 6x12x1.5 : P220006 : T4006012 0/000.440.9124 (u. 1)
31	RJ-MR ELECTRIC STARTER COVER : EE85100GG-CLJ-1 0/000.220.9119 (u. 1)
32	ALLEN BOLT 6x45 : T0306045 0/000.460.9149 (u. 1)
33	SPECIAL SCREW 6x40 : T0306040 0/000.460.9148 (u. 1)
34	HEAD SCREW 6x50 : T0206050 0/000.460.9126 (u. 1)
35	(ENDURO) BRUSH START REPAIR KIT EE80010GG-CBR-1 (u. 1)
36	RJ-GENERATOR {RIEJU MR 21->} 0/005.820.9103 (u. 1)